## CONTRACT CHANGE ORDER MEMORANDUM

TO: Pete Siege	nthaler, F	Prin TE /			FILE:	E.A.	04 - 0120F4			
FROM: Kannu Balan, Senior TE						E-PM D. NO.	SF-80-13.2/13.9			
CCO#: <b>143</b>	SUPPL	EMENT#: 0	Category	Code: CHPT	CONTINGENCY BALANCE (incl. this change) \$166,431,208.11					
COST: \$362	2,231.00	INCR	EASE 🗹	DECREASE	HEADQUARTERS APPROVAL REQUIRED? ✓ YES ☐ NO					
SUPPLEMENTAL FUNDS PROVIDED: \$0.00						IS THIS REQUEST IN ACCORDANCE WITH    ✓ YES    NO ENVIRONMENTAL DOCUMENTS?				
CCO DESCRIPTION: Floorbeam Diaphragms						PROJECT DESCRIPTION: CONSTRUCT SELF-ANCHORED SUSPENSION BRIDGE				
Original Contract Time:		Time Adj. This Change:		Previously Approved CCO Time Adjustments:		,		Total # of Unreconciled Deferred Time CCO(s): (including this change)		
2490	Day(s)	n	Dav(s)	501 Da	v(s)		20 %	2		

DATE: 8/4/2011

Page 1 of 2

## THIS CHANGE ORDER PROVIDES FOR:

For Orthotropic Box Girder (OBG) Lifts 6w and 7 through 12, verifying the plumbness of the floorbeam diaphragms and performing heat distortion straightening. For OBG Lifts 13 and 14, changing the deck plate diaphragm to floorbeam flange welds from double filet welds to full depth PJP welds.

Revising Special Provisions Section 10-1.59 "STEEL STRUCTURES," subsection "Shop Welding," subsection "Design Details."

The Department instituted new acceptance criteria for the floorbeam diaphragms affecting both in progress and completed work. Therefore, the Contractor needs to perform extra work to validate compliance and rework floor beams that are not in compliance. Floorbeams in Lifts 6w and 7 through 12 that did not comply were heat straightened to bring them within the tolerance provided under this change. On Lifts 13 and 14, the weld is changed to increase misalignment tolerance and distortion tolerance, and minimize the need for heat straightening or retrofit.

Additional field work to take measurements and perform retrofit measures at OBG Lifts 1 through 5 and 6E will be addressed in a supplemental change order.

This change order resolves the costs associated with Contractor Request for Information (RFI) numbers 2083R0, 2083R1, 2083R2, and TC-RFI-0067R0 with respect to changes listed above.

The total cost of this change order is \$362,231.00, which can be financed from the contingency fund. A detailed cost analysis is on file.

No time adjustment is warranted, as this change order does not affect the controlling operation.

This change order has concurrence from Peter Siegenthaler (Principal TE), William Casey (Sup. TE), Ken Terpstra (Project Manager), Rich Foley (HQ Oversight), Lina Ellis (Maintenance) and Wenyi Long (Design Oversight).

The Resident Engineer requests Headquarters CCO Desk "Issue and Approve".

EA: 0120F4 CCO: 143 - 0

DATE: 8/4/2011

Page 2 of 2

CONCURRED BY:		ESTIMATE OF COST						
Construction Engineer: PCE, Pete Siegenthaler, Prin T		Date	8/24/10		THIS REQUEST		TOTAL TO DATE	
Bridge Engineer:	William Casey, Sup TE	Date 8/23/10		ITEMS	\$0.00		\$0.00	
Project Engineer:	CT Oversight, Wenyi Long, P.E.	Date	8/11/10	FORCE ACCOUNT	\$0.00 \$362,231.00		\$0.00	
Troject Engineer.	CT Oversight, Wellyl Long, F.E.	Date	6/11/10	AGREED PRICE			\$362,231.00	
Project Manager:	Proj Manager, Ken Terpstra	Date	8/25/10	ADJUSTMENT	\$0.00	)	\$0.00	
FHWA Rep.:				TOTAL	\$362,231.00	)	\$362,231.00	
Environmental:				FEDERAL PARTICIPATION				
0" ( ",		Date		PARTICIPATING	PARTICIPATING	G IN PART	✓ NONE	
Other (specify): HQ, Rich Foley		Date	8/24/10	NON-PARTICIPATING (MAINTENANCE)			PARTICIPATING	
Other (specify):	Struct. Maint, Lina Ellis	Date	8/4/11	FEDERAL SEGREGATION (if more than one Funding Source or P.I.P. type				
District Prior Approval By: HQ, Larry Salhaney		Date	9/1/10	CCO FUNDED PER CONTRACT CCO FUNDED AS FOL				
HQ (Issue Approve) By: Dat								
The (Issue Approve) by.				FEDERAL FUNDING	SOURCE	PERCEN	NT.	
Resident Engineer's Signature:				(4	0.00			
Kambal			4/11					
		1.5	1				-	